

Modiri Molema Road DPW Provincial Head Office Mmabatho, 2735 Private Bag X 2037, Mmabatho, 2735

Tel.: +27 (18) 387 2002 Fax.: +27 (18) 387 2868

At least five employees- cleaning staff- were slightly injured...

Date: Thursday, May 28, 2009

At least five employees- cleaning staff- were slightly injured during a scramble at exit points following an explosion of the electrical distribution board which caused panic and within seconds plunged a section of the Old Parliament Building into darkness.

The explosion happened on the ground floor at about 9.30am and disrupted some scheduled activities and well as normal working operations.

The injuries were not caused by electrical shocks. Rather from a near stampede as elderly employees rushed for a quick escape through the doors and windows after a loud bang.

Our investigation confirmed that the cause of the explosion was the liquid acid detergent, stored in a plastic container above, and leaked into the electrical tubing.

The overnight flow ultimately caused an electrical short circuit that lead to an explosion.

Seconds after the explosion, smoke engulfed the ground floor where the circuit board is located; resulting in a commotion as panicking employees ran for cover.

Some employees reportedly jumped through the windows to safety and one employee suffered a small cut on the head while the others sustained minor injuries.

According to our inspectors, it may take a while before power is restored to the affected sections as the circuit board will need to be re-wired.

The department takes the safety of all its employees seriously.

End

